

CAIXAS

DE VISITA OU INSPEÇÃO

CAIXAS	DIMENSÕES (mm)			
	L comp. medidas úteis	W larg. medidas úteis	h alt. exterior	t espess.
Com fundo	400	400	460	40
	500	500	480	50
	600	600	550	60
	800	800	780	80
	1000	1000	1000	100
Sem fundo	300	300	250	40
	400	400	510	40
	500	500	250	50
	500	500	530	50
	600	600	600	60
	670	670	540	68
	800	800	500	80
	800	800	830	80
	900	800	500	150
	1000	1000	500	100
	1000	1000	1100	100

